

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



COMPOSITE COATINGS FOR GROUND WALL INSULATION IN MOTORS, METHOD OF MANUFACTURE THEREOF
AND ARTICLES DERIVED THEREFROM

Asokan et al.

ATTORNEY DOCKET NO. 130507-1

Serial No. 10/627,480

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002

1/20

FIG. 1




FIG. 2




FIG. 3B




FIG. 3A





FIG. 4



COMPOSITE COATINGS FOR GROUND WALL INSULATION IN MOTORS, METHOD OF MANUFACTURE THEREOF
AND ARTICLES DERIVED THEREFROM

Asokan et al.


ATTORNEY DOCKET NO. 130507-1

Serial No. 10/627,480

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002

5/20

FIG. 5



6/20

FIG. 6




FIG. 7





FIG. 8



9/20

FIG. 9B





FIG. 9A



10/20

FIG. 10




FIG. 11





FIG. 12



COMPOSITE COATINGS FOR GROUND WALL INSULATION IN MOTORS, METHOD OF MANUFACTURE THEREOF
AND ARTICLES DERIVED THEREFROM

Asokan et al.

ATTORNEY DOCKET NO. 130507-1

Serial No. 10/627,480

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002

13/20

FIG. 13




FIG. 14




FIG. 15




FIG. 16B





FIG. 16A



Asokan et al.

ATTORNEY DOCKET NO. 130507-1

Serial No. 10/627,480

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002

17/20

FIG. 17B




FIG. 17A




FIG. 18B




FIG. 18A




FIG. 19B





FIG. 19A



20/20

FIG. 20B




FIG. 20A

